

PARTS BULLETIN

PB15-004

Date:2015-04-30

Page 1/4

Product	Container Handlers
Type/Model	DRF, DRT, DCF, DCF360-520+CSG, DRG
Subject	Standard Filter kits
From dept.	Technical Sales Support
Group	0004

To whom it may concern,

Filter kits are available for machines with following specification. Note! Only standard filters, no options are included.

Model DRF400-450 with 920871.0136 TAD1360VE and 923892.0016 ZF5WG261

425803.0100	belt kit
425803.0101	50 h service
425803.0102	500 h service
425803.0103	1000 h service
425803.0104	2000 h service

Model DRF400-450 with 922784.0038 QSM11 3A and 922297.0170 15.7TE32418-82

425803.0200	belt kit
425803.0201	50 h service
425803.0202	500 h service
425803.0203	1000 h service
425803.0204	2000 h service

Model DRF400-450 with 922784.0036 QSM11 3A and 923892.0010 ZF5WG261

425803.0300	belt kit
425803.0301	50 h service
425803.0302	500 h service
425803.0303	1000 h service
425803.0304	2000 h service



Model DRF400-450 with 920871.0112 TAD1250VE and 922297.0170 15.7TE32418-82

425803.0400	belt kit
425803.0401	50 h service
425803.0402	500 h service
425803.0403	1000 h service
425803.0404	2000 h service

Model DRT450 with 922784.0037 QSM11 3A and 922297.0169 15.5HR36432-34

belt kit
50 h service
500 h service
1000 h service
2000 h service

Model DRT450 with 924425.0001 YUCHAI YC6M360-30S and 922297.0169 15.5HR36432-34

425803.0600	belt kit
425803.0601	50 h service
425803.0602	250 h service
425803.0603	500 h service
425803.0604	1000 h service
425803.0605	2000 h service

Model DCF360-520+CSG with 920871.0118 TAD952VE and 922297.0170 15.7TE32418-82

425801.1900	belt kit
425801.1901	50 h service
425801.1902	500 h service
425801.1903	1000/2000 h service

Model DCF360-520+CSG with 920871.0112 TAD1250VE and 922297.0170 15.7TE32418-82

425801.2000	belt kit
425801.2001	50 h service
425801.2002	500 h service
425801.2003	1000/2000 h service

Model DCF360-520+CSG with 922784.0038 QSM11 and 922297.0170 15.7TE32418-82

belt kit
50 h service
500 h service
1000/2000 h service



Model DCF360-520+CSG with 920871.0149 TAD1360VE and 922297.0170 15.7TE32418-82

belt kit
50 h service
500 h service
1000 h service
2000 h service

Model DRF100 with 920871.0110 TAD760VE and 922297.0179 340FTE17311-60

425803.0700	belt kit
425803.0701	50 h service
425803.0702	500 h service
425803.0703	1000 h service
425803.0704	2000 h service

Model DRF100 with 920871.0148 TAD762VE and 922297.0179 340FTE17311-60

425803.0800	belt kit
425803.0801	50 h service
425803.0802	500 h service
425803.0803	1000 h service
425803.0804	2000 h service

Model DRF100 with 922784.0033 QSB6.7 164KW and 922297.0179 340FTE17311-60

425803.0900	belt kit
425803.0901	50 h service
425803.0902	500 h service
425803.0903	1000 h service
425803.0904	2000 h service

Model DRF420-450L with 922784.0037 QSM11 224KW and 922297.0170 15.7TE32418-82

425803.1000	belt kit
425803.1001	50 h service
425803.1002	500 h service
425803.1003	1000/2000 h service

Model DRG400-450 with 920871.0168 TAD1360VE and 923892.0025 ZF5WG261

425803.1100	belt kit
425803.1101	50 h service
425803.1102	500 h service
425803.1103	1000 h service
425803.1103	2000 h service



Model DRG400-450 with 922784.0036 QSM11 3A and 923892.0010 ZF5WG261

425803.1200	belt kit
425803.1201	50 h service
425803.1202	500 h service
425803.1203	1000 h service
425803.1204	2000 h service

If you have any questions, please contact: ks.parts@kalmarglobal.com